

NAVAL RESEARCH LAB WASHINGTON DC F/6 13/
MERCURY CONTAMINATION OF A COMMUNITY WATER SUPPLY DIAGNOSIS AND--ET
JUL 82 J C COOPER, C J HACKBARTH, C M HELLWIG

AND--ET

NRL-MR-4845

NL

104
AD A
1987

END
DATE
FILMED
8-82
DTIC

D
NRL

AD A116379

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NRL Memorandum Report 4845	2. GOVT ACCESSION NO. AD A116370	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) MERCURY CONTAMINATION OF A COMMUNITY WATER SUPPLY - DIAGNOSIS AND RESTORATION	5. TYPE OF REPORT & PERIOD COVERED Final report.	
7. AUTHOR(s) J.C. Cooper, C.J. Hackbarth, C.M. Hellwig, Rm. Panayappan, and D.L. Venezky	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Naval Research Laboratory Washington, DC 20375	8. CONTRACT OR GRANT NUMBER(s)	
11. CONTROLLING OFFICE NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 61-0027-0-2	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	12. REPORT DATE July 7, 1982	
	13. NUMBER OF PAGES 42	
	15. SECURITY CLASS. (of this report) UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Mercury Contamination Water supply Chemical cleaning		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) A community water supply was contaminated by mercury from a flow meter. The subsequent chemical analyses, sampling methods and chemical cleaning methods employed for diagnosing and resolving the problem are described. The results show (1) that significant errors in evaluating such a problem could result from inadequate or incorrect sampling methods or sampling site selection, (2) that complications in the interpretation of the results arise from the chemistry of the water system and the surfaces of the plumbing system, and (3) that small portions of the water system are likely to be major sources of contamination and can be cleaned efficiently by chemical means. Recommendations are made concerning the use of mercury-containing flow meters.		

DD FORM 1473
1 JAN 73

EDITION OF 1 NOV 65 IS OBSOLETE
S/N 0102-014-6601

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

CONTENTS

INTRODUCTION.....	1
EXPERIMENTAL PROCEDURES.....	5
Samples	
Analysis Methods	
ANALYSIS AND RESOLUTION.....	8
Localization of Mercury	
Cleaning Operations	
Continued Monitoring	
SAMPLING PROBLEMS AND SCAVENGING OF MERCURY BY IRON OXIDES.....	14
ACCURACY AND PRECISION.....	20
CONCLUSIONS AND RECOMMENDATIONS.....	22
ACKNOWLEDGMENT	24
APPENDIX.....	25
REFERENCES.....	38



Accession For
 BUREAU OF
 THE
 U.S. DEPT. OF
 AGRICULTURE
 OFFICE OF
 THE
 SECRETARY
 WASHINGTON, D. C.

MERCURY CONTAMINATION OF A COMMUNITY WATER SUPPLY DIAGNOSIS AND RESTORATION

John C. Cooper, Claudia J. Hackbarth, Christine M. Hellwig,
Rm. Panayappan and David L. Venezky
Inorganic and Electrochemistry Branch
Chemistry Division

INTRODUCTION

This report describes the occurrence of a mercury spill, discovered in early March of 1978, from a mercury-filled flow meter into a community water supply and the subsequent evaluation and correction of the problem. Difficulties encountered with sampling methods and with standard methods for analysis of mercury could complicate the diagnosis and resolution of similar problems in other drinking water supplies. Such other occurrences are likely since mercury-containing flow meters are in common use. The information presented here should help to prevent such incidents and if they do occur, significantly aid in their resolution.

The water supply studied consists of two operating wells, each approximately 500 feet deep, in different aquifers pumping on demand into either the distribution system with a volume of about 150,000 gallons or a 100-foot-high reservoir tower with a capacity of about 500,000 gallons. The system supplies water to about 25 residences in addition to laboratory buildings, involving a total of about 250 people. Figure 1 shows the general layout of the distribution system. The majority of the main distribution lines are 14-inch and smaller transite pipe. Some areas, such as the distribution valves and plumbing near the water tower are cast iron and provided a significant complication in the spread of mercury into the distribution system.

Figure 2 shows the relationship of the well pumphouse where the mercury entered the system to the water tower and distribution valve area. The 8-inch well is a total of 540 feet deep through alternating shale and sandy loam aquifers. A submersible pump and a check valve are located at the bottom of a 240 foot inner sleeve of 4-inch black iron. The actual water level is approximately 100 feet above the pump under normal conditions. A mercury flow meter of a Ledoux Bell design (Figure 3) measures water flow by calculation of the pressure differential on either side of a standard orifice. The combined effect of a faulty check valve above the pump, the location of the




Fig. 1 - Drinking water distribution system major features, CBD/NRL.
Routine sampling locations indicated.




Fig. 2 - Schematic of well system. (not to scale).




Fig. 3 - Approximate design of mercury flow-meter which delivered mercury into water system.

mercury flow meter with respect to a second functional check valve and the limited tolerable pressure differential of the flow meter was to siphon mercury from the flow meter into the line leading from the well. Immediate action was taken to prevent further contamination, diagnose the problem, and restore the system to safe concentrations of mercury. The sequence of events to accomplish these goals are reported here, and the appendix tabulates, chronologically, mean values of analyses performed through October, 1978.

EXPERIMENTAL PROCEDURES

Samples were collected in new, conventional polyethylene bottles which had been pretreated by soaking with 50% nitric acid for at least 24 hours, followed by a thorough rinsing with pure water (Milli-Q-process, producing water of higher overall quality than ASTM Type III: ASTM-D1193-77). During the first phases of sampling, a blank containing Millipore water traveled with the sample bottles throughout and always measured below our detection limit of 0.18 $\mu\text{g/l}$ (ppb). Some bottles containing samples measuring less than 7 $\mu\text{g/l}$ in total mercury were recycled by soaking with nitric acid as above.

Initial experiments showed no detectable leaching of mercury from such recycled bottles even after standing several weeks. Subsequently however, it was found that solutions containing a known amount of additional mercury typically showed analytical results lower than expected, presumably due to surface scavenging of mercury by residual materials (probably iron oxides) not completely removed by the cleaning process, or by otherwise activated surface materials. Although a substantial fraction of samples were collected in recycled bottles, the slight amount of mercury loss combined with timely analyses ensured that this phenomenon did not in any way affect any of the conclusions.

If more than 48 hours were to pass between time of sampling and analysis, samples were acidified with nitric acid to $\text{pH}=2.0$. As a result, no differentiation between oxidation state of mercury in the samples could be made in those cases. With the exception of re-runs of older samples and similar studies of day-to-day repeatability and sample aging experiments, in excess of 95% of the samples were analyzed within 48 hours of sampling, and none were held more than 96 hours before analysis.

To avoid the inconveniences which a random sampling method would impose upon residential users, a plan for continuous monitoring of selected locations was devised, coupled with occasional sampling of all residences. Occasional additional sampling points were added at random as a check on the statistical validity of the selected loca-

tions. Three residences were chosen so as to allow sampling of three main portions of the distribution system (Fig. 1). In addition, regular sampling was done at Building 6 (a location used for some specific tests of sampling methods), pump house 6 (the contaminated well), and pump house 7 (to insure the integrity of the water supply in use and to check for possible geological migration from well no. 6). Sampling at these locations was done on a weekly schedule with additional sampling during periods of system perturbation.

Analysis Methods. With the exception of some x-ray fluorescence analyses² done to verify results and to aid in differentiation of oxidation state, all mercury analyses were performed using the standard EPA method of manual cold-vapor atomic absorption.³ Initial analyses showed no organic mercury compounds present. The mercury analysis equipment is shown in Figure 4. Analyses were performed on one of two instruments - a Perkin-Elmer 460 double-beam or P.E. 272 single-beam atomic absorption spectrometer. In both cases, a mercury hollow-cathode lamp was used and the measurement was made at the 253.7 nm line of mercury. With the exception of a difference in absorbance vs. concentration slopes for the two instruments, error-of-measurement data showed no significant differences between the two instruments, provided the single-beam instrument was re-zeroed frequently enough to correct for its continuous drifting.

Unless otherwise stated, mercury analytical results are for total mercury. The sample was homogenized by vigorous shaking before removing an aliquot and the reported results are for three or more runs with standard deviation less than 10% of the value reported. Samples showing greater than 11 µg/l for a 100 ml aliquot were diluted and rerun. Mercury in solids such as scale was determined by digesting weighed samples in boiling aqua regia for at least four hours and diluting with water. Standard addition experiments⁴ established a lower detection limit of 0.18 µg/l using water samples from the water system. Operator-to-operator variations and volumetric errors were found to be insignificant. The only significant contributions to measurement error were due to the sampling itself.

Analyses for iron and copper in the various cleaning operations were done by standard flame atomic-absorption methods.³

Auger measurements⁵ on scale inside the cast-iron plumbing in the valve-pit area involved standard methods. However, considerable vacuum drying was required, possibly causing some loss of elemental mercury.

Reagents were all of ACS Reagent Grade or higher purity. The chemicals for the cold vapor mercury analyses were specially prepared




Fig. 4 - Cold - vapor mercury analysis system.

to be low in mercury. Standards were freshly prepared each day from 0.001 to 0.1 M stock solutions by serial dilution. In the case of the mercury standards, two stock solutions from entirely unrelated sources were prepared by different operators. Analyses by both AA and by x-ray fluorescence gave results in agreement within experimental error in both cases.

ANALYSIS AND RESOLUTION

The first evidence that a problem existed was the indication from flow meter service personnel that several pounds (between 7 and 14.5 lbs) of mercury had been replaced. Subsequent analysis of a single sample from a residential location (Quarters A in Fig. 1) showed a total mercury concentration of 97 $\mu\text{g}/\text{l}$, a level some fifty-fold higher than the established maximum permissible level for public drinking water supplies of 2 $\mu\text{g}/\text{l}$ ⁶ and some 2000 to 5000 times the likely background levels.^{7,8}

Immediate action was taken to prevent further contamination. The well and associated plumbing were isolated from the distribution system. The offending flow meter and one at a second well site (pump house no. 7 in Fig. 1) were irreversibly removed from the system. Physical removal of contaminated water and any localized pools of mercury was initiated by flushing the entire distribution system with water from the reservoir tower. At this point, efforts were begun to determine (1) the extent of the spread of elemental mercury into the system, (2) the true system level of mercury, and (3) the location of the bulk of the mercury. At the same time, studies were undertaken to validate our sampling methods. In addition, because the mercury concentration was at the body-burden level and because the duration of the problem was uncertain, personnel using the water system were screened⁹ (single-void urine samples) for mercury-poisoning. Results indicated essentially normal levels of mercury (about 5 $\mu\text{g}/\text{l}$) in urine of all residents, suggesting the contamination was recent. In addition analyses of ice cubes, an emergency water supply, and water from a closed-off portion of the distribution system showed the problem to be less than 6 months, but more than two weeks old.

Localization of Mercury. The water system itself provided complications which would likely spread mercury throughout the distribution system and which made distribution of the mercury difficult to determine. First, there are at least three possible oxidizing agents or catalysts for the ready conversion of elemental mercury to soluble mercury(II) which would readily spread: dissolved oxygen, chlorine from the chlorination systems located in each pump house at the outlet of the well, and iron(III) present in scale in the plumbing. Second,

the system operates so that water is pumped by either pump into the reservoir or into the distribution system as needed, thus making impossible any prediction of the direction elemental mercury droplets might be conveyed. Third, sampling points were not readily available in the general vicinity of the flow meter.

After an initial determination by selected sampling that mercury at levels above 20 $\mu\text{g}/\text{l}$ was to be found in each major section of the system, a program was begun of physically flushing the distribution system with water from the reservoir (up to 1/2 million gallons each time at once-or twice-weekly intervals). A comprehensive sampling was done of all residences and such other sampling points as were accessible to provide enough data to allow statistically valid conclusions about levels of mercury in various parts of the system.

Initial results after several physical flushing operations indicated the following: (1) levels of total mercury were generally about the same, ranging from 6 to 20 $\mu\text{g}/\text{l}$ at the cold water taps indicating thorough distribution, (2) the lower elevation locations (near Quarters I in Fig. 1) were generally at the high end of this range, (3) the uncontaminated well was usually at or below our estimated detection limit of 0.18 $\mu\text{g}/\text{l}$ mercury, indicating no appreciable geological migration from the possibly contaminated well to the lower aquifer of well no. 7, (4) mercury levels at a sampling tap near the chlorination equipment of pump house no. 6 were often in excess of 200 $\mu\text{g}/\text{l}$ with visible mercury droplets sometimes observed, (5) sampling from the bowl of the reservoir tower showed levels similar to the rest of the system, but the mercury was nearly all in the suspended solids (5 to 8 $\mu\text{g}/\text{l}$ total Hg) and not in solution (0.3 $\mu\text{g}/\text{l}$ soluble Hg), (6) samples taken from drain taps of hot water heaters in residences were sometimes very high in total mercury (several greater than 100 $\mu\text{g}/\text{l}$, highest was 1500 $\mu\text{g}/\text{l}$) and subsequent analyses showed the mercury in these samples to be nearly all in the suspended solids (soluble mercury was less than the total mercury level of the corresponding cold water sample).

At this point, it was apparent that the physical flushing of the distribution system had reduced somewhat the overall levels of mercury in spite of concern that this might further distribute any local concentrations of elemental mercury. It was also apparent that mercury existed in the system as soluble mercury(II), elemental mercury, and possibly as a mercury(I) compound in the suspended solids. In addition, much higher mercury concentrations in samples near pump house 6 and very high concentrations in samples from a tap in the pump house indicted the bulk of the mercury was still in the vicinity of pump house 6.

Inasmuch as high levels of mercury were found in the vicinity of pump house 6, two portions of the system were opened for sampling. The plumbing at the point of attachment of the flow meter contained approximately 1.5 lbs. of elemental mercury, mostly in the dead space of 'TEE's' and valves. The entire section of lines in the pump house, up to the well head, was dismantled and physically cleaned. In addition, the distribution valve area, the next accessible portion of the system near pump house 6 and common to the water tower and the distribution system (see inset in Figure 1), was entered by removing a section of pipe outside the pit area and two valve stems in the pit. Although there were no large pools of elemental mercury, some mercury droplets were found and the soluble mercury levels were considerably higher (about 70 $\mu\text{g/l}$) than at the end points of the distribution system. In addition, scrapings of the scale from inside plumbing in the pit area had high mercury levels (0.05% by weight). Tests using uncontaminated water standing in the section of pipe that was removed gave 20 $\mu\text{g/l}$ levels of total mercury in the water after standing one hour. A significant portion of the soluble mercury in the distribution system could be leaching from the iron-oxide scale. It was determined that some sort of cleaning of this portion of the system would be required. In addition, since these operations had not accounted for the bulk of the approximately 14 lbs. of mercury thought to have entered the system, it was likely in the well. Very high levels (sometimes greater than 1000 $\mu\text{g/l}$ and containing droplets of mercury) in water pumped from well no. 6 into a collecting tank confirmed this latter point. It would therefore be necessary to clean the well.

Cleaning Operations. The cost of a new well and the risk of further environmental damage from a contaminated abandoned well required a method of removal of mercury from the well or insurance of its non-mobility. In addition, the area of greatest quantity of iron pipe and therefore mercury laden scale, the valve-pit area, required cleaning to restore it to service.

A chemical cleaning method was devised for the distribution valve area, based in part on generally used procedures for hot-water boiler cleaning and cleaning of metal surfaces in ship bilge areas. In order to evaluate the quantity of chemicals required and the need for removing scale, an Auger analysis was made of both sides of a carefully removed piece of scale. The iron oxide scale was typical, consisting of a magnetite layer (Fe_3O_4) separating the iron pipe from a porous surface coating of Fe_2O_3 (see Figure 5). The Auger




Fig. 5 - Model of iron oxide scale formed on surface of iron plumbing.

results and mercury analyses of a small section of the scale sample indicated that all mercury was contained in the outermost portion of the magnetite layer and the Fe_2O_3 layer. Cleaning would therefore require little disruption of the protective inner magnetite coating. This result was confirmed by carefully separating portions of scale from both sides of a scale sample - only the exposed Fe_2O_3 surface contained appreciable amounts of mercury. A multi-step process was developed, beginning with acid-catalyzed chelation to remove the bulk of the mercury. The formulation chosen was a mixture of ethylenediaminetetraacetic acid (EDTA) and citric acid (H-Cit). Laboratory experiments using the removed section of 14-inch cast iron pipe allowed optimization of pH and concentrations. Citric acid and EDTA were chosen for two reasons. First, citric acid, acting as a general acid, can catalyze dissolution and complexation of hydrous iron oxides, thus increasing the rate at which mercury is liberated from the scale and available for complexing. Secondly, both citrate and EDTA have favorable formation constants for mercury(II) complexes compared to iron(II). The first formation constants are summarized in Table 1.

Table 1: Log of formation constants (K_1) for complexes of Hg^{2+} , Fe^{2+} and Fe^{3+} with citrate and EDTA (from references 10-12).

	log K_1		
	Hg^{2+}	Fe^{2+}	Fe^{3+}
citrate:	11.	4.4	11.
EDTA:	22.	14.	25.

The iron(III) formation constant is sufficiently high to insure its complete removal with the mercury. The lower formation constant for iron(II) and the inert nature of the magnetite layer would likely leave it intact. A scheme was devised to clean with the EDTA/citric acid mixture, follow with oxidation by chlorine of elemental mercury or mercury(I) left in the surface of the magnetite and clean again

with EDTA/citric acid to remove the oxidized mercury.

In preparation for this cleaning operation, valves were closed to isolate the entire distribution valve area and tower from the distribution system. Pressure was maintained in the distribution system by means of a surge tank attached to well no. 7 to avoid any back-flow of cleaning chemicals into the water supply. The setup operations uncovered a previously unknown "dirt leg" in the base of the tower which contained considerable amounts of mercury. In addition, portions of zinc sacrificial electrodes from the water tower contained as much as 0.1% mercury.

The EDTA/citric acid formulation devised was 125 lbs. Hampene NA3T (Na_3HEDTA) and 100 lbs of citric acid in about 400 gallons of water heated to about 60°C while circulating through the system. This mixture gave the optimum final pH of 3.5 and still allowed fairly high concentrations of the EDTA. After cleaning with citric acid/EDTA, the system was flushed with water and treated with super-chlorinated water (1 lb. $\text{Ca}(\text{OCl})_2$ in 400 gal) to oxidize any mercury(0) or mercury(I) to soluble mercury(II), and finally by another EDTA-citric acid treatment. The cleaning was monitored by mercury and iron analyses. The results are shown in Figure 6. Several important points are evident in these results: (1) The second EDTA-citrate treatment removed a proportionately much smaller amount of mercury, indicating that only a small portion was present as elemental mercury or mercury(I) and that the initial cleaning was very successful. (2) The chlorination did not remove iron (magnetite). (3) The total amount of mercury removed agreed fairly well with estimates based on mercury concentration in the scale samples.

After flushing the cleaned area, the tower and distribution valve area were returned to service.

Disposal of used cleaning solution must be considered very carefully. Available disposal options may indeed dictate the choice of cleaning methods. Regulations limiting the discharge of water containing high levels of heavy metals and the environmental impact of simple discharge of such wastes¹³ demand careful advance planning for proper disposal. In addition, recent literature implicating chelating agents such as EDTA in geological migration of heavy metals and radio-isotopes^{14,15} require decomposition of this component to weakly or non-coordinating species. In the present case, the choices for proper disposal were quickly reduced to two options: (a) removal of mercury as precipitated sediment and slow discharge into the local sewage treatment system or (b) combustion with a scrubber-equipped high temperature incinerator. Either option would have been satisfactory. Cost of option (a) would have been considerably less, but would have




Fig. 6 - Iron and mercury analyses during clean-up of distribution value area.

to be done over an extended period of time to avoid swamping the bacteria in the tertiary system with EDTA. We were, however, relieved of the need for such a choice by individuals anxious to recover the temporary storage tank holding the waste. Acting in spite of impending plans for proper disposal, and in direct disregard for environmental consequences, these individuals discharged the waste cleaning solution onto the ground near the eastern shore of the Potomac River. Upon learning of this "spill" it was determined by consultation with local environmental authorities that no potable water intakes were present for several miles downstream of the discharge point and that the slow leaching into the river would not cause sufficient problems to warrant recovery efforts. This unfortunate incident should reinforce the need for careful advance planning for proper disposal.

The well, where high mercury concentrations indicated most of the mercury had gone, was cleaned by removing the inner 4-inch sleeve and pump and using an air-lift method to blow out the sediment and water in the well. Levels of mercury higher than 1% by weight were found in the scale inside the 4-inch inner pipe. It was therefore replaced. The pump, composed mostly of brass, was successfully cleaned with a dilute mixture of Na_3HEDTA and was returned to service. The debris and water removed from the well contained large amounts of mercury (as high as 14,000 ppb total). After the air-lift operation, levels of mercury in the well were down to 1.5 to 2.1 $\mu\text{g}/\text{l}$ and the well was subsequently returned to service after a two-month period of monitoring with levels consistently below 0.2 $\mu\text{g}/\text{l}$.

Continued Monitoring. Results of analyses of the four monitoring points to mid-October, 1978 are shown in Figure 7. There is an approximately exponential overall decay of mercury in the system as reflected at these sampling points. The initial wide variations are likely due to the frequent flushing of the distribution system. Most other variations can be explained by analysis of the sampling conditions and provide important information regarding the uncontrolled variables in the sampling of such a system. The system as a whole remained well below the 2 $\mu\text{g}/\text{l}$ EPA limit after October 1, 1978. Periodic monitoring was maintained for several months to insure the integrity of the water system as the restored well was brought back on line and to satisfy Federal analysis requirements for post-contamination situations.

SAMPLING PROBLEMS AND SCAVENGING OF MERCURY BY IRON OXIDES

The scavenging of mercury by iron oxide scale poses a complication to sampling. After finding that most of the plumbing leading from the main to the individual residences and inside the residences




Fig. 7 - Mercury analyses at routine sampling points, quarters A (O), quarters I (●), quarters W-3 (Δ), and bldg. 6 coffee mess (□).

was iron, it became apparent that some of the variations seen in Figure 7 were due to leaching of mercury from the scale into water standing in these pipes. The data beginning in mid-July reflect an attempt to control this variable by running the tap long enough before sampling to flush the local plumbing. A calculation indicated that two minutes should be adequate in all cases at full flow to flush the standing water and provide a representative sample from the main. Except for the results of Qtrs. I, which was undergoing plumbing repair during this period which presumably dislodged scale, this sample control seemed to provide results indicative of mercury concentrations in the system as a whole. It did mean, however, that considerable time would be required to remove by flushing the remainder of the mercury entrained in scale in the local plumbing.

This leaching of mercury from surfaces of iron plumbing also implies that for several samples on a given day, the minimum value should approach the bulk system mercury concentration. Therefore, it is likely that general trends in the system mercury concentration can be obtained from the earlier data by considering such a minimum value from several samples on a given day. It is assumed that the system variation is much smaller than the individual variations with length of time the water has been sitting in the local plumbing. Accordingly, Figure 8 shows the high, mean, and low values of the four samples at each date. Changes in the low value with time are considerably smoother than the fluctuations observed at any one location. There are some common fluctuations with the mean and high values, indicating some system variations. The above assumption of a wide local variation with time is supported by several experiments where sequential samples were collected at a given location. Figure 9 is typical of these results. There is always a substantial decline in mercury level as water is removed and the initial level is dependent on the length of time since the tap was last used.

The scavenging of mercury by iron oxide, was studied to determine the mechanism involved. Several different iron oxides from different sources were treated with solutions containing mercury. The experiment involved magnetite (Fe_3O_4) - both commercially available reagent and prepared from metallic iron and mild steel oxidized with air and HCl , and Fe_2O_3 from commercial sources and prepared by treatment of iron and mild steel with nitric acid. Samples of each of the above were treated with a real sample which contained 28 $\mu\text{g/l}$ Hg, a mercury(II) solution (1000 $\mu\text{g/l}$), tap water (less than 0.2 $\mu\text{g/l}$ Hg) and pure water. Without exception, the magnetite (Fe_3O_4) samples removed mercury from solution. The results were dramatic: excess Fe_3O_4 removes more than 90% of the soluble mercury, but Fe_2O_3 has little effect.




Fig. 8 - Mercury analyses at routine sampling points, highest value (Δ), mean (O), and lowest value (\square).





Fig. 9 - Mercury analyses of sequential samples collected at bldg. 6 site.
(Error bars are $\pm \sigma$.)

It is possible that other materials such as precipitated carbonates are also involved in such processes, but clearly the magnetite is. Experiments with the entrained mercury in magnetite equilibrated with pure water and mercury-free tap water showed slow (minutes to hours) equilibration of the mercury, which is consistent with the observations of mercury levels in water standing in iron plumbing—both the local plumbing and laboratory experiments with the inner surface of the piece of 14-inch cast iron pipe. This slow equilibration also indicates that an ion-exchange mechanism may be involved in addition to or rather than reduction of the mercury(II). Such a phenomenon might usefully be applied as a filter for cleaning mercury from a polluted water supply.

A possible mechanism for transport of mercury within the water-Fe₂O₃-magnetite system involves reduction of the mercury(II) by iron(II):



Oxidation by dissolved oxygen or chlorine would readily cause the mercury to re-dissolve. In addition, presence of organic acids, amines, and chloride could alter the normally unfavorable reverse process,



by the shifts in reduction and oxidation potentials that always occur with complexation.

Considerable recent work¹⁶⁻¹⁸ has quantified physical adsorption of mercury on hydrated Fe₂O₃, but no previous work was found implicating magnetite in such processes. Scavenging by iron(III) oxides and sulfides and some silicates are apparently responsible for reasonably low levels of mercury in normal surface waters¹⁹ and the ocean²⁰ as well as migration of mercury and other heavy metals within the environment.²¹ In the case of the sulfides, insolubility of mercury(II) sulfide is clearly the major factor¹³, and mercury(II) presumably binds to polymeric iron(III) oxides/hydroxides by simple complexation. Whether an ion-exchange process operates in the case of iron(II) and iron(III) oxides was not determined by our preliminary experiments.

An interpretation consistent with these observations can be made of the related sampling problem involving recycled sample bottles. Residual iron oxides remaining on the polyethylene surface from which

mercury has been removed by cleaning with nitric acid are then able to scavenge mercury from subsequent solutions. Entrainment of cations by such a mechanism is consistent with ion-exchange properties of many inorganic materials.²²

A final sampling problem involves the slow oxidation of elemental mercury by oxygen and perhaps by nitric-acid passivated polyethylene. Our initial experiments indicated that previous estimates²³ for the solubility of elemental mercury in water may be erroneously high. This would also complicate differentiation between oxidation states of mercury in real samples.

ACCURACY AND PRECISION

Accuracy of analytical results was assured by following standard and accepted methodology³ and by occasional determinations using a totally independent analytical method², particularly in the earlier analyses. The two methods were generally in agreement within 10% of the values obtained. The x-ray fluorescence method generally showed somewhat lower mercury concentrations than the cold vapor AA method. Using standard samples, it was determined that a slow loss of mercury occurred during x-ray fluorescence analyses and is presumed to be due to volatilization of elemental mercury by x-rays in the evacuated sample compartment.

Precision measurements were vigorously maintained through the resolution of the problem and into October of 1978. These efforts consisted of (a) multiple-operator correlations, which showed no significant variations, (b) repeated determination of standard curves, (c) standard addition experiments to allow estimate of lower detection limits using real samples, (d) dilution experiments with samples having mercury concentrations near 10 µg/l, and (e) replicate analyses. Replicate sampling and significance testing (Student's t-test) demonstrated (a) the leaching of mercury from scale described above and shown in figure 9, (b) the non-uniformity of the distribution system both temporally and spatially, and (c) inhomogeneity of six early high level samples near pump house 6 -- repeated analyses with more vigorously homogenized samples and care in dilution eliminated this problem.

That volumetric errors contributed no systematic error and that precision followed a relationship to concentration usual for chemical analyses²⁴⁻²⁷ is shown in figure 10. Least-squares lines for data with no dilution (slope= 0.0042 ± 0.006), samples diluted 1:2 (slope= 0.019 ± 0.004) and samples diluted 1:10 (slope= 0.036 ± 0.02) show the expected increase in slope with concentration. Data where significant particulates or elemental




Fig. 10 - Analytical precision as a function of concentration.
 * = 1:10 dilution, 0 = 1:2 dilution, + = no dilution.

mercury was present in the sample were excluded from this analysis. To a first approximation, standard deviation (σ) was a linear function of concentration within one dilution range. Of course, the usual definition of detection limit²⁸ requires that σ become much higher relative to concentration as one approaches the detection limit. That such a result is not seen here is due to (a) few data near the detection limit and (b) a likely true detection limit below the value determined by standard addition experiments. Figure 11 shows variation of standard deviation as a function of mercury concentration for the two different instruments used for undiluted samples. Least-square lines show some differences (lower line for P.E. 460). The single-beam Perkin-Elmer 272 is clearly less stable in spite of more frequent calibration. Results, however, were still within the approximately 10% error range.

Mean mercury concentrations for samples taken through October of 1978 are tabulated in the appendix. Following October, replicate runs were generally reduced to two analyses per sample and all results were well below the 2 $\mu\text{g}/\text{l}$ Interim Standards requirement.

CONCLUSIONS AND RECOMMENDATIONS

It is clear that malfunctioning or incorrectly installed mercury-containing water flow meters in use in public drinking water systems pose a significant threat to health. It is also clear that the time and expense involved in correcting a mercury spill of this sort is significant. It is recommended that water supplies using mercury flow meters of this sort insure that they are correctly installed, that regular mercury analyses be performed, and that no mercury be added to such meters without suspecting loss into the system and determining its destination.

A simpler solution is to remove these meters altogether. It is likely that sufficiently accurate flow measurements can be obtained with other devices or by monitoring the time that pumps are running.

The presence of iron oxide scale in plumbing systems can have a significant impact on the accurate diagnosis of a mercury contamination problem, and more importantly, can serve as a mercury buffer, resulting in a lower system concentration and minimizing the health impact.

Finally, proper disposal of waste cleaning solutions containing mercury or EDTA is very important. Simple discharge into the environment is unsatisfactory from the standpoint of mercury pollution¹³ or the migration of heavy metals or radioisotopes which the EDTA would cause.^{14,15} In the case described here, proper disposal by (a)

Standard Deviation of Mean $\times 10^{**} 1$




Fig. 11 - Analytical precision as a function of concentration for two instruments used. P.E.460 is lower least-squares line (+), P.E.272 is upper least-squares line (0).

removal of mercury as precipitated sediment and slow discharge into the local sewage treatment system or (b) combustion with a scrubber-equipped high-temperature incinerator was obviated when individuals aware of the potential risks involved dumped the waste solution on the ground near the Potomac River.

ACKNOWLEDGMENT

We are deeply indebted to Robert Conlyn, Station Engineer at Chesapeake Bay Division, NRL, without whose careful study of the missing mercury situation this problem would not have come to light and without whose patience and engineering expertise it could not have been resolved. Cooperation from Duane A. Geuder, Gabe Lapidus and J. Dakita of the District of Columbia Department of Environmental Services in the form of the loan of considerable amounts of reagents in short supply is gratefully acknowledged. Assistance from John F. Murray and Robert L. Shuler, who performed some of the nearly two thousand individual mercury analyses, was greatly appreciated.

APPENDIX

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
3-10-78	1	97(80)	Qtrs A cw	
3-15-78	1	25(19)	Qtrs B cw	
	2	20,21ss	Qtrs J grape Koolaid	
	3	25(19)	Bldg 6 coffee mess	
3-20-78	1	1.	Emergency supply	(6 years old)
	2	20(12,(1.3ss)	Qtrs A cw	
	3	10(10,(1.3ss)	Qtrs W13 cw	
	4	20(15,(1.3ss)	Qtrs J cw	
	5	1(3.3,(1.3ss)	Pump House 7	
3-22-78	1	18	Qtrs A cw	
	2	21	Qtrs I cw	
	3	12	Qtrs W13 cw	
	4	15	Bldg 6 coffee mess	
	5	(.2	Pump House 7	
	6	(9)	Pump House 6, check side	contained Hg droplets
	7	(54)	Pump House 6, well	contained Hg droplets
	8	9.9	"Hollow" area	(old water)
3-24-78	1	19	Qtrs A cw	
	2	12	Qtrs I cw	
	3	8	Qtrs W13 cw	
	4	11	Bldg 6 coffee mess	
	5	(.2	Pump House 7	
	6	(208)	Pump House 6 check side	contained Hg droplets
	7	(93)	Pump House 6 well	contained Hg droplets
	8	(.2	NRL 207/313 cw	
	A	7.7	Tower before flush	
	B,C	5(.3)	Tower sludge	
3-28-78	1	7.4	Qtrs A cw	
	2	13	Qtrs B cw	
	3	17	Qtrs C cw	
	4	10	Qtrs D cw	
	5	18	Qtrs E cw	
	6	19	Qtrs F cw	
	7	9.7	Qtrs G cw	
	8	18	Qtrs H cw	
	9	17	Qtrs I cw	
	10	7.0	Qtrs J cw	
	11	6.0	Qtrs W1 cw	
	12	6.7	Qtrs W2 cw	
	13	7.5	Qtrs W3 cw	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	14	7.2	Qtrs W4 cw	
	15	4.5	Qtrs W5 cw	
	16	4.7	Qtrs W6 cw	
	17	3.3	Qtrs W7 cw	
	18	8.3	Qtrs W8 cw	
	19	5.6	Qtrs W9 cw	
	20	11	Qtrs W10 cw	
	21	3.2	Qtrs W11 cw	
	22	7.1	Qtrs W12 cw	
	23	10	Qtrs W13 cw	
	24	11	Qtrs W15 cw	
	25	6.1	Bldg 6 coffee mess	
	26	.2	Store, Randaes Cliff	
	27	(272)	Pump House 6 sample tap	contained Hg droplets
	28	(.2	Pump House 7 sample tap	
	29	(.2	Bay water at pier	
	30	19	Qtrs A hw	
	31	17	Qtrs B hw	
	32	8.3	Qtrs C hw	
	33	5.2	Qtrs D hw	
	34	3.5	Qtrs W1 hw	
	35	(4.5)	Qtrs W2 hw	
	36	62	Qtrs W3 hw	
	37	16(18)	Qtrs W4 hw	
	38	18(4.2)	Qtrs W5 hw	
	39	86(5.0)	Qtrs W6 hw	
	40	101(6.7)	Qtrs W7 hw	
	41	32(5.0)	Qtrs W8 hw	
	42	>1500(14)	Qtrs W9 hw	
	43	57(1.2)	Qtrs W10 hw	
	44	84(4.2)	Qtrs W11 hw	
	45	(2.1)	Qtrs W12 hw	
	46	224(5.2)	Qtrs W13 hw	
	47	232	Qtrs W15 hw	
	A	(.2	Qtrs A outside tap	Overlook Ave
3-30-79	1	151	Hydrant at Whirling Arm	
	2	(67)	Pump House 6 well	
	3	(.2	Pump House 7	
	4	6.9	Qtrs W3 cw	
	5	13	Qtrs A cw	
	6	9.3	Bldg 6 coffee mess	
	7	(5.3)	Pump House 6 upper tap	
	8	.3	Bldg 4 ice cubes	spec 1 (3/26)
	9	1	Bldg 4 ice cubes	spec 2 (3/28)

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	10	.5	Bldg 75 ice cubes	spec 1 rm 308 (3/28)
	11	(.2	Bldg 75 ice cubes	spec 2 (3/28)
	12	(.2	Bldg 75 ice cubes	spec 3 (3/29)
	13	(.2	Bldg 75 ice cubes	spec 4 (3/29)
	14	(.1200)	1500 gal tank and hose	sediment: contained Hg droplets
4-04-78	1	22	Qtrs A cw	
	2	28	Qtrs J cw	
	3	12	Qtrs W3 cw	
	4	17	Bldg 6 coffee mess	
	5	.7	Pump House 7 sample tap	
	6	26	Pump House 6, well	
4-10-78	1	14	Qtrs A cw	
	2	18	Qtrs J cw	
	3	7.7	Qtrs W3 cw	
	4	9.4	Bldg 6 coffee mess	
	5	(.2	Pump House 7	
	6	248	Pump House 6, well	
	7	30(9.6)	Qtrs A hw	
	8	9.6	Qtrs B hw	
	9	14	Qtrs C hw	
	10	6.6	Qtrs D hw	
	11	16	Qtrs E hw	
	12	13	Qtrs F hw	
	13	15	Qtrs G hw	
	14	18	Qtrs H hw	
	15	31	Qtrs I hw	
	16	11	Qtrs J hw	
	17	5.9	Qtrs W1 hw	
	18	6.5	Qtrs W2 hw	
	19	4.6	Qtrs W3 hw	
	20	6.9	Qtrs W4 hw	
	21	3.4	Qtrs W5 hw	
	22	6.9	Qtrs W6 hw	
	23	5.1	Qtrs W7 hw	
	24	6.3	Qtrs W8 hw	
	25	10	Qtrs W9 hw	
	26	8.2	Qtrs W10 hw	
	27	12	Qtrs W11 hw	
	28	5.4	Qtrs W12 hw	
	29	6.2	Qtrs W13 hw	
	30	8.1	Qtrs W15 hw	
4-17-78	1	13	Qtrs A cw	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	2	12	Qtrs J cw	
	3	8.3	Qtrs W3 cw	
	4	8.4	Bldg 6 coffee mess	
	5	1.4	Pump House 7	
	6	330	Pump House 6 sample tap	
	7	51	Pump House 6 sample tap	4 min. after start-up
	8	51	Pump House 6 boiler drain	
	9	11	open tank bottom drain	
	A	[.026]	Open Tank, sediment	as mg Hg / g of sediment(sand)
4-20-78	A	[.019]	Open Tank, Sediment	as mg Hg / g of sediment(sand)
4-21-78	1	22(13)	14" cast-iron pipe	after breaking
	2	400(70.)	bottom of 14" valve	after removing Tee
	3	460	bottom of 6" valve	tower side of 14" valve
	A	[.54]	Main TEE scrapings	(from Fox)
4-24-78	1	4.8	Qtrs A cw	
	2	5.0	Qtrs W3 cw	
	3	8.3	Qtrs J cw	
	4	5.3	Bldg 6 coffee mess	
	5	224(100)	Pump House 6 sample tap	
	6	31(20)	Pump House 6 sample tap	4 min after start-up
	7	343(96)	Pump House 6 open tank	
	8	12((.2)	Pump House 7 sample tap	
	9	392(11.)	14" transite line	
4-25-78	1	5.6	Bldg 6 coffee mess	time=0800
	2	5.6	Bldg 6 coffee mess	time=0900
	3	4.4	Bldg 6 coffee mess	time=1000
	4	4.5	Bldg 6 coffee mess	time=1100
	5	4.0	Bldg 6 coffee mess	time=1200
	6	6.1	Bldg 6 coffee mess	time=1300
	7	5.6	Bldg 6 coffee mess	time=1400
	8	4.2	Bldg 6 coffee mess	time=1500
	9	2.6	Bldg 6 coffee mess	time=1600
4-28-78	1	6.4	Bldg 6 coffee mess	sample 1
	2	4.7	Bldg 6 coffee mess	sample 2
	3	4.6	Bldg 6 coffee mess	sample 3
	4	4.4	Bldg 6 coffee mess	sample 4
	5	4.1	Bldg 6 coffee mess	sample 5
	6	4.3	Bldg 6 coffee mess	sample 6
	7	9.9	Qtrs A cw	
	8	13.4(8.4)	Qtrs W3 cw	
	9	11.7	Qtrs I cw	

SAMPLE DATE	NO.	Hg (PPM)	SAMPLE LOCATION	COMMENTS
	10	6.2(4.9)	Pump House 6, open tank	
	11	.20(.26)	Pump House 7	
5-3-78	1	4.8	Qtrs A cw	
	2	9.0	Qtrs I cw	
	3	4.6	Qtrs W3 cw	
	4	4.9	Bldg 6 coffee mess	
	5	1.2(1.2)	Pump House 7 sample tap	
	6	15000(350)	Pump House 6 sample tap	at start up
	7	74(68)	Pump House 6 sample tap	2 min after start up
	8	26(19)	Pump House 6 sample tap	4 min after start up
	9	16(10)	Pump House 6 sample tap	10 min after start up
	10	27(15)	Pump House 6 open tank	
5-8-78	1	4.2	Qtrs A cw	
	2	9.0	Qtrs I cw	
	3	4.0	Qtrs W3 cw	
	4	1.2(1.2)	Pump House 7 sample tap	
	5	5.8	Bldg 6 coffee mess	
	6	68	Pump House 6	at start-up
	7	11	Pump House 6	after 2 min
	8	11	Pump House 6	after 4 min
	9	8.0(4.4)	Pump House 6	after 10 min
	10	4.3(3.2)	Pump House 6 open tank	
	11	(35)	Pump House 6 open tank	sand and sediment
5-17-78	1	4.8	Qtrs A cw	
	2	1.0	Qtrs I cw	
	3	2.8	Qtrs W3 cw	
	4	3.7	Bldg 6 coffee mess cw	
	5	1.2	Pump House 7 sample tap	
	6	96(34)	Pump House 6 sample tap	at start-up
5-22-78	1	4.0	Qtrs A cw	
	2	7.2	Qtrs I cw	
	3	1.2	Pump House 7 sample tap	
	4	3.6	Qtrs W3 cw	
	5	3.8	Bldg 6 coffee mess	
	6	63(31)	Pump House 6 sample tap	at start up
5-30-78	1	4.8	Qtrs A cw	
	2	7.6	Qtrs I cw	
	3	1.2	Pump House 7 sample tap	
	4	4.4	Qtrs W3 cw	
	5	2.9	Bldg 6 coffee mess	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	6	127	Pump House 6 sample tap at start-up	
5-31-78	1	7.9	Hot water, before pumping into system	
	2	13.2	Sample tap off standpipe in pit	
	3	21.9	From 400 gallon tank	
	4A	70	Liquid over sludge in 4' riser	
	4B	[.024]	Sludge from 4' riser	
	5	[.0056]	From 8" into 4' riser sludge	
	Rod	[.083]	Dry encrustation from Zn rod	
6-1-78	1	12.4	400 gallon tank hw	
	2	24.1	400 gallon tank before EDTA added	
	3	260	400 gallon tank at 13:40	
	4	590	400 gallon tank at 13:55	
	5	785	400 gallon tank at 14:30	
	6	[.00035]	Bottom of 4' riser	
	7	[.00076]	1.5' from bottom of 4' riser	
	8	760	400 gallon tank at shutdown, 15:35	
6-2-78	1	56	Sample from 8" drain at 08:15	
	2	41.2	Sample from 8" drain at 08:15	
	3	36	Sample from 8" drain at 08:15	
	4	17	"Dirt leg" at base of tank	
	5	146	Superchlorinated	
	6	20	14" riser after chlorination, 1hr rest	
	7	51	400 gal tank after 2nd clean-up w/ EDTA/citrate	
	8	[.0040]	Sand from bottom of 4' riser after cleaning	
	9	[.023]	Outside scrapings from 14" pipe at waterline	
	10	[.023]	Outside scrapings from 14" pipe " below ledge	
	11	[.089]	Inside scrapings from 4' pipe above water line	
	12	[.0011]	Dip from 14" riser wet	
	13	[.0028]	Dip from 14" riser wet	
6-5-78	1	14	Discharge from 8" drain	
	2	9	4' standpipe	
	3	38	1" valve in pit	
6-6-78	1	6.4	Holding tank after 10 min. circulation	
	2	5.5	4' dirt leg after sitting overnite	
	3	5.6	14" riser after sitting overnite	
6-7-78	1	3.4	Bottom of 4' riser	
	2	2.6	14" riser	
	3	3.3	Open tank (400 gal. tank?)	
	4	4.8	Qtrs. W-3, cu	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	5	7.9	Qtrs.I, cw	
	6	3.2	Bldg #6 Coffee mess	
	7	2.1	Qtrs.A, cw	
	8	.2	Pumphouse #7, Sample tap at start-up	
6-12-78	1	[.95]	Down end of "T" at top of well	
	3	[15.9]	Bottom of 1st pipe section, inside	
	5	[11.1]	Bottom of 2nd pipe section, inside	
	6	[.017]	Bottom of 2nd pipe section, outside	
	8	[10.7]	Bottom of 3rd pipe section, inside	
	10	[13.0]	Bottom of 4th pipe section, inside	
	12	[7.3]	Bottom of 5th pipe section, inside	
	14	[5.0]	Bottom of 6th pipe section, inside	
	16	[6.8]	Bottom of 7th pipe section, inside	
	17	[.067]	Bottom of 7th pipe section, outside	
	19	[3.7]	Bottom of 8th pipe section, inside	
	21	[6.9]	Bottom of 9th pipe section, inside	
	22	[7.0]	Top of 10th pipe section, inside	
	23	[7.2]	Bottom of 10th pipe section, inside	
	24	[5.9]	Bottom of 10th pipe section, inside cufflink	
	25	[10.6]	Top of 11th pipe section, inside	
	27	[.065]	Intake screen debris & around joint	
	28	[.46]	Intake screen debris & around joint	
	29	[.66]	Inside check valve	
	30	[.23]	Top end of pump pipe	
	31	2.9	Bldg.#6, Coffee mess	
	32	620	Pumphouse #6 at start-up, sample tap	
	33	2.7	Qtrs.W-3, cw	
	34	8.3	Qtrs.I, cw	
	35	140	Pumphouse #6, Sample tap 6 min after start-up	
	36	1.45	Qtrs.A, cw	
	37	(.2	Pumphouse #7, Sample tap at start-up	
6-13-78	1	60	Water standing 24hrs in pump before flushing	
	2	120	Start of pump flushing, Test #1	
	3	28	Draining from 1500 gal tank after initial flush	
	4	210	Settled matter from pump-1st flush (Test #2)	
	5	100	EDTA poured through pump 3 times	
	6	1.8	1500 gal tank final drain-off out of pump	
6-14-78	1	38	Well blow-out, 1 min after start	
	2	82(14)	Well blow-out at 09:41	
	3	180(35)	Well blow-out at 09:43 color change	
	4	800(180)	Well blow-out at 09:45	
	5	170(11)	Well blow-out at 09:51	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	6	66(20.4)	Well blow-out at 09:57	Last sample
6-15-78	1	18(16)	Well blow-out at 11:11	
	6	110(1.0)	Well blow-out at 11:17	
	12	2400(140)	Well blow-out	
	25	60(27)	Well blow-out at 13:02 (Resumed at 12:57)	
	26	1394(206)	1500 gal tank, Morning's accumulation	
	A	1.0096	Scrapings from well casing, 509' depth & up	
6-16-78	1	430(1.0)	Air jet at 525' level at start of pumping	
	2	12300(40)	"Bottom load" 3 min after start of pumping	
	3	20(6.2)	20 min after start of pumping, running clear	
	4	750(59)	Composite from drain of 1500 gal tank	
	A	1.070	Sludge from 1500 gal tank from 6-15 air pumping	
6-19-78	1	3.3	Qtrs. I cw	Soddy
	2	7.9	Qtrs. A cw	
	3	2.3	Qtrs. W-3 cw	
	4	3.5	Pump House 7 Sample tap at start-up	
	5	1.9	Bldg. #6 coffee mess	
	6	2560	From lower drain, 1500 gal tank after 1/2 full	
	6A	.55	Filtrate from 6-19-78 #6	
	6B	1.601	Solids from 6-19-78 #6	
	7	53(40.)	Last water from hose at 528' level	
	8	34(1.6)	From 531' level	
6-20-78	1	1340(284)	Well filled back from 535'-532', top of fill	
	2	3.5	Qtrs. I cw	
	3	7.1	Qtrs. A cw	
	4	2.1	Qtrs. W-3 cw	
	5	1.2	Pumphouse #7 Sample tap	
	6	1.5	Bldg. #6 coffee mess	
	7	20.0	Well depth of 537' at 08:43	
	8	25.6	Well depth of 538' at 09:01	
	9	24.6	Well depth of 539' at 09:31	
	10	25	Well depth of 542' at 10:08	
	11	1.7	Well depth of 535' before pumping stopped @ 17:00	
6-21-78	1	18.4	From EDTA holding tank	
	2	26.2	From EDTA holding tank	
	3	140	From pump cleaning EDTA soln. @ 11:45	
	4	128.	From pump cleaning EDTA soln. @ 12:45	
6-22-78	1	5.3	Drawn from screen	
	2	1.2	Disconnected from lead packer-Drawn from well as a whole	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
6-26-78	1	2.6	Qtrs. W-3 cw	
	2	1.2	Pumphouse #7 Sample tap	
	3	3.8	Qtrs. A cw	
	4	4.3	Qtrs. I cw	
	5	4.6	Bldg. #6 coffee mess	
6-27-78	1	38	From "dirt leg" at base of riser (400 xG tank)	
6-28-78	1	2.2	Qtrs. W-3 cw	
	2	1.2	Pumphouse #7 sample tap	
	3	6.7	Qtrs. A cw	
	4	4.9	Qtrs. I cw	
	5	.96	Bldg. #6 coffee mess	
7-3-78	1	1.1	Qtrs. W-3 cw	
	2	1.2	Pumphouse #7 sample tap	
	3	2.2	Qtrs. A cw	
	4	4.6	Qtrs. I cw	
	5	1.7	Bldg. #6 coffee mess	
7-6-78	1	0.14	Pump-washing tank prior to pump immersion	
7-7-78	1	3.1	Pump-washing tank after pump soaked	
7-10-78	1	3.0	Qtrs. W-3 cw	
	2	.31	Pumphouse #7 sample tap	
	3	12.9	Qtrs. A cw	
	4	1.8	Qtrs. I cw	
	5	4.0	Bldg. #6 coffee mess	
7-17-78	1	.83	Qtrs. W-3 cw	
	2	1.2	Pumphouse #7 sample tap (black sand in bottle)	
	3	.6	Qtrs. A cw	
	4	2.1	Qtrs. I cw	
	5	1.3	Bldg. #6 coffee mess	
7-26-78	1	1.1	Qtrs. W-3 cw after 2 minutes	
	2	1.2	Pumphouse #7 sample tap after 2 min.	
	3	1.0	Qtrs. A cw after 2 min.	
	4	2.9	Qtrs. I cw after 2 min.	
	5	.7	Bldg. #6 coffee mess after 2 min.	
8-2-78	1	.7	Qtrs. W-3 cw after 2 minutes	
	2	1.2	Pumphouse #7 sample tap after 2 min.	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	3	1.01	Qtrs. A cw after 2 minutes	
	4	3.9	Qtrs. I cw after 2 minutes	
	5	1.1	Bldg. #6 coffee mess after 2 min.	
8-9-78	1	.8	Qtrs. W-3 cw after 2 minutes	
	2	1.2	Pumphouse #7 sample tap after 2 min.	
	3	3.0	Qtrs. A cw after 2 minutes	
	4	11.1	Qtrs. I cw after 2 minutes	
	5	.2	Bldg. #6 coffee mess after 2 min.	
8-16-78	1	5.7	Qtrs. W-3 cw First water	
	2	.7	Qtrs. W-3 cw after 2 minutes	
	3	1.2	Pumphouse #7 after 2 minutes	
	4	1.5	Qtrs. A cw First water	
	5	1.1	Qtrs. A cw after 2 minutes	
	6	5.1	Qtrs. I cw First water	
	7	2.2	Qtrs. I cw after 2 minutes	
	8	3.7	Bldg. #6 coffee mess First water	
	9	1.2	Bldg. #6 coffee mess after 2 minutes	
8-23-78	1	.5	Qtrs. W-3 cw after 2 minutes	
	2	1.2	Pumphouse #7 after 2 minutes	
	3	1.1	Qtrs. A cw after 2 minutes	
	4	2.4	Qtrs. I cw after 2 minutes	
	5	2.2	Bldg. #6 cw coffee mess after 2 minutes	
8-30-78	1	0.2	Qtrs W-3 cw after 2 min.	
	2	1.2	Pump House 7	
	3	.9	Qtrs A cw after 2 min.	
	4	1.5	Qtrs I cw after 2 min	
	5	3.3	Bldg 6 coffee mess cw after 2 min.	
9-1-78	1	156(129)	Pump House 6 well bottom sample	
9-6-78	1	800	Pump House 6 blow-out sample 1	
	2	1.1	Pump House 6 blow-out 2 min	
	3	3.8	Pump House 6 blow-out at 4 min	
	4	2.1	Pump House 6 blow out at 10 min	
9-7-79	1	.5	Pump House 6 2nd blow-out 0 min	
	2	1.8	Pump House 6 2nd blow-out 2 min	
	3	11.9	Pump House 6 2nd blow-out 4 min	
	4	1.2	Pump House 6 2nd blow-out 10 min	
9-8-79	1	.7	Pump House 6, pump on 37 min	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	2	1.4	Pump House 6, pump on 10 min	
	3	11.6	Pump House 6, pump on 4 min	
	4	1.9	Pump House 6, pump on 2 min	
	5	6.8	Pump House 6, pump on 0 min	
	6	.6	Pump House 6, pump on 1 hr	
	7	1.3	Pump House 6, pump off 4 hr, on 10 min	
9-9-78	1	18.4((.2)	Pump House 6 at 0 min	
	2	5.1((.2)	Pump House 6 at 2 min	
	3	1.1((.2)	Pump House 6 at 4 min	
	4	.8	Pump House 6 at 10 min	
	5	(.2	Pump House 6 at 8 hr	
9-11-78	1	4.0	Pump House 6 at 0 min	
	2	5.1	Pump House 6 at 2 min	
	3	.7	Pump House 6 at 4 min	
	4	.3	Pump House 6 at 10 min	
9-12-78	1	1.9	Pump House 6 at 0 min	
	2	6.6	Pump House 6 at 2 min	
	3	2.1	Pump House 6 at 4 min	
	4	.3	Pump House 6 at 10 min	
	5	(.2	"stream fall"	
9-13-78	1	1.3	Pump House 6 at 0 min	
	2	1.9	Pump House 6 at 2 min	
	3	.3	Pump House 6 at 4 min	
	4	(.2	Pump House 6 at 10 min	
	5	.3	Pump House 6 at 4 hr	
	6	(.2	"stream fall"	
	7	.2	Qtrs W-3 cw after 2 min	
	8	.2	Pump House 7 after 2 min	
	9	.7	Qtrs A cw after 2 min	
	10	1.4	Qtrs I cw after 2 min	
	11	(.2	Bldg 6 cw coffee mess after 2 min	
	12	.8	Pump House 6 after 4 hr	
9-14-78	1	(.2	Pump House 6 at 0 min	
	2	(.2	Pump House 6 at 1 min	
	3	.5	Pump House 6 at 2 min	
	4	(.2	Pump House 6 at 3 min	
	5	(.2	Pump House 6 at 4 min	
	6	(.2	Pump House 6 at 10 min	
	7	(.2	Pump House 6 at 1 hr	
	8	(.2	"stream fall"	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
9-18-78	1	13.0	Pump House 6 at 0 min	
	2	.3	Pump House 6 at 1 min	
	3	1.2	Pump House 6 at 2 min	
	4	2.3	Pump House 6 at 3 min	
	5	1.2	Pump House 6 at 4 min	
	6	1.2	Pump House 6 at 10 min	
9-20-78	1	1.3	Pump House 6 Boiler drain at 0 min	
	2	2.9	Pump House 6 Boiler drain at 2 min	
	3	3.6	Pump House 6 Sample tap at 0 min	
	4	7.8	Pump House 6 Sample tap at 2 min	
	5	2.2	Pump House 6 Sample tap at 4 min	
	6	1.3	Pump House 6 Sample tap at 10 min	
9-21-78	1	1.8	Pump House 6 Sample tap at 0 min	
	2	1.6	Pump House 6 Sample tap at 2 min	
	3	1.2	Pump House 6 Sample tap at 10 min	
	4	1.2	Pump House 6 Sample tap at 20 min	
	5	1.2	Pump House 6 Sample tap at 2 hr	
9-22-78	1	.6	Qtrs W-3 cw at 2 min	
	2	1.0	Pump House 6 sample tap at 2 min	
	3	1.0	Qtrs A cw at 2 min	
	4	1.2	Qtrs I cw at 2 min	
	5	.8	Bldg 6 coffee mess cw at 2 min	
9-25-78	1	1.6	Qtrs A cw at 2 min	
	2	2.2	Qtrs I cw at 2 min	
	3	.45	Qtrs W-3 cw at 2 min	
	4	1.0	Bldg 6 coffee mess cw	
	5	2.2	Pump House 6 at 2 min	
	6	1.2	"Stream fallout" 100 feet from bay	
9-26-78	1	.65	Qtrs A cw at 2 min	
	2	1.9	Qtrs I cw at 2 min	
	3	.79	Qtrs W-3 cw at 2 min	
	4	.7	Bldg 6 coffee mess cw at 2 min	
	5	.36	Pump House 6 at 2 min	
	6	1.2	"Sample stream, 100 ft."	
9-27-78	1	3.8	Qtrs A cw at 2 min	
	2	1.3	Qtrs I cw at 2 min	
	3	.6	Qtrs W-3 cw at 2 min	
	4	3.2	Bldg 6 coffee mess cw at 2 min	

SAMPLE DATE	NO.	Hg (PPB)	SAMPLE LOCATION	COMMENTS
	5	.2	Pump House 6 at 2 min	
10-2-78	1	.4	Qtrs A cw at 2 min	
	2	1.3	Qtrs I cw at 2 min	
	3	.2	Qtrs W-3 at 2 min	
	4	1.0	Bldg 6 coffee mess cw at 2 min	
	5	.7	Pump House 5 at 2 min	
10-4-78	1	.4	Qtrs A cw at 2 min	
	2	1.2	Qtrs I cw at 2 min	
	3	.35	Qtrs W-3 cw at 2 min	
	4	.6	Bldg 6 coffee mess cw at 2 min	
	5	1.0	Pump House 6 at 2 min	
10-11-78	1	.5	Qtrs A cw at 2 min	
	2	1.0	Qtrs I cw at 2 min	
	3	.3	Qtrs W-3 cw at 2 min	
	4	.8	Bldg 6 coffee mess cw at 2 min	
	5	.7	Pump House 6 sample tap at 2 min	

NOTES:

- ppb = parts per billion (micrograms per liter of sample)
- ss = suspended solids
- cw = cold water (in residences, from kitchen)
- hw = hot water (from drain on water heater)
- spec = specimen
- () indicate analyses performed by x-ray fluorescence
- () indicate results for supernatant liquid only
(does not include suspended solids)
- [] indicate analyses of solid samples and are reported as
mg of mercury (total) per g of solid

REFERENCES

1. A preliminary report of this project was presented at the Pittsburgh Conference on Analytical Chemistry and Applied Spectroscopy, Cleveland, Ohio, March 5, 1979.
2. For description of x-ray fluorescence analysis methods see R. Panayappan, D. L. Venezky, J. V. Gilfrich, and L. S. Birks, "Determination of Soluble Elements in Water by X-ray Fluorescence Spectrometry after Preconcentration with Polyvinylpyrrolidone - Thionalide," Anal. Chem., 50, 1125 (1978).
3. "Methods for Chemical Analysis of Water and Wastes," EPA-625-/6-74-003 Washington, D.C. (1974).
4. See for example Robert Klein, Jr. and Clifford Hach, Am. Lab., 9, 21 (1977).
5. We are indebted to James S. Murday of Surface Chemistry Branch, NRL, for performing Auger measurements on scale samples.
6. "Primary Drinking Water, Proposed Interim Standards," Federal Register, 40 (51), 11990, March 14, 1975.
7. William F. Fitzgerald, Limn. and Oceanog., 20, 468 (1975).
8. Herbert V. Weiss, Thomas E. Cozier, Anal. Chim. Acta, 58, 231 (1972).
9. Performed by J. Wright, Naval Environmental Health Center, Cincinnati, Ohio using cold vapour AA methods described in P. and C.A.M. No. 165 for Urine, Vol. 1 (NIOSH).
10. L. G. Sillen and A. E. Martell, "Stability Constants of Metal-ion Complexes," Special Publication No. 17, The Chemical Society, London, 1964.
11. L. G. Sillen and A. E. Martell, "Stability Constants of Metal-ion Complexes, Supplement No. 1," Special Publication 25, The Chemical Society, London, 1971.
12. A. E. Martell and Robert M. Smith, "Critical Stability Constants," Vol. 3, Plenum, N. Y., 1977.

13. R. P. Eganhouse, J. N. Johnson, D. R. Young, and D. J. McDermott, "Mercury in Southern California Waters: Inputs, Distribution, and Fate," Summary Rpt., 1971-75, SCCWRP-TM227-76.
14. Jeffrey L. Means, David A. Crerar, and James O. Duguid, "Migration of Radioactive Wastes: Radionuclide Mobilization by Complexing Agents," Science, 200, 1477 (1978).
15. Luther J. Carter, Science, 200, 1135 (1978).
16. Peter Avotins, "Adsorption and Coprecipitation Studies of Mercury on Hydrous Iron Oxide," Ph.D. Dissertation, Stanford University, 1975.
17. K. C. Swallow and Francois Morel, "Adsorption of Trace Metals by Hydrous Ferric Oxide in Seawater," EPA-600/3-80-011, January, 1980.
18. D. G. Kinniburgh and M. L. Jackson, "Adsorption of Mercury(II) by Iron Hydrous Oxide Gel," Soil Sci. Soc. Am. J., 42, 45 (1978).
19. James R. Brown, G. Michael Bancroft, William S. Fyfe, and Ronald A. N. McLean, "Mercury Removal from Water by Iron Sulfide Minerals. An Electron Spectroscopy for Chemical Analysis (ESCA) Study," Envir. Sci. Tech., 13, 1143 (1979).
20. Prithviraj Mukherji and Dana R. Kester, "Mercury Distribution in the Gulf Stream," Science, 204, 64 (1979).
21. E. L. Schrader and William J. Furbish, "An Aqueous and Sedimentological Model for Heavy Metal Contamination of Stream Systems Affected by Sulfide Mining in the Eastern United States," Bull. Environm. Contam. Toxicol., 20, 159 (1978).
22. See for example, P. U. Sakellaris and F. Z. Nobelis, J. Inorg. Nucl. Chem., 36, 2599 (1974).
23. E. Onat, J. Inorg. Nucl. Chem., 36, 2029 (1974).
24. K. Z. Doerffel, Z. Anal. Chem., 185, 91 (1962).
25. R. Puschel, Mikrochim. Acta, 783 (1968).

26. E. Lassner, Z. Anal. Chem., 222, 170 (1966).
27. E. Schwarz-Bergkamp, Z. Anal. Chem., 221, 143 (1966).
28. Sabina Slavin, William B. Barnett and Herbert L. Kahn, Atomic Absorption Newsletter, 11, 37 (1972).

8F